

COPY.

# Lloyd's Register of Shipping.



Port BANGKOK.

17th January, 1939.

**This is to Certify** *that I have*

*parts of the*  
*Surveyed the Boiler and Machinery of the M.V. "MALINI" No. 78916*  
*in the Register Book,*

*and that I have transmitted to the Committee of Lloyd's*  
*Register of Shipping, London, a Report stating that all*  
*recommendations made by me in connection therewith have*  
*been carried out to my satisfaction, and that I have*  
**Recommended** *that the record of + L.M.C.(C.S.) with date*

*be made in the Register Book in the case of this vessel when*  
*the survey has been completed.*

Parts now examined:—

No. 5 stard. Cylinder, piston, valves, gears and cover.  
Connecting rod, top end, bottom end and crankpin.

No. 2 Diesel generator complete with compressor and  
starting air bottle New crankshaft (No. 4352 19:10:38) and main  
bearings fitted.


Main engine. Port and stard. Main compressor inter-  
coolers. Port engine lubricating oil pump.  
Sea Connections.

*L. A. Richardson*

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly  
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
to be held responsible for any inaccuracy in any report or Certificate issued by the Society or its Surveyors, or in any  
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its  
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register  
Foundation