

25 JUN 1942

COPY

# Lloyd's Register of Shipping.

High Close, Wokingham, Berks.

29th June, 1942.


H. Dear Sirs,

With reference to your report No.54305 on the motorship "KING ARTHUR", I shall be glad if you will point out to the Owners' Superintendent that the following parts of the machinery have not been submitted to inspection for over four years, and should be examined as suitable opportunities present themselves:-

- No.4 main crank pin.
- Starting air receiver for the dynamo engines.
- Injection air receivers for the forward and aft dynamo engines.
- Nos. 1 and 5 main engine crossheads.
- Forward dynamo engine and its compressor.
- The outboard main starting air receiver.

I am, Dear Sirs,  
Yours faithfully,

The Surveyors,  
CARDIFF.



Clerk to the  
Classification Committee.

Lloyd's Register  
Foundation

W46-0186

Delete from S.R.L:- Dry docking. Rivets in E.R. cofferdam.

*at all said high read of survey 6, 42, subject to*