

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

13th July, 1934.

Dear Sirs,

With reference to your letter of the 12th instant advising your Report C.11 and Form Req. 9 in respect of the motorship "NORA MAERSK", I shall be glad if you will forward two copies of the Midship Section and General Arrangement plans of this vessel, as required by Circular 1483, and also two copies of the Displacement Scale.

At the same time you should state the bearing surface of the webs of Nos. 1 and 2 hatchways on the superstructure deck, and verify the bearing surface of the webs of Nos. 1, 2, 3, 4 and 5 hatchways on the freeboard deck (reported by you as being 70 mm) as this is required to be 75 mm by Rule XII of the Convention. Further, you should advise me if the trimming hatchways on the freeboard deck are fitted with tarpaulins, cleats and battens, giving particulars thereof.

I am, Dear Sirs,

Yours faithfully,

The Surveyors,

COPENHAGEN.

Secretary.



© 2020

Lloyd's Register
Foundation

W464-0207