

14658

16883

FREEBOARD VERIFICATION FORM FOR STEAMERS.

MON. 18 JUN 1906

When received in London Office

Name Glasgow
S/S. "Bairnform"
 No. 119113 No. in Reg. Book 67 71
 Registry (For Foreign Vessels) ☒
 Steel Steel State whether Classed by Lloyd's Register +100 A.1
 of Owners W. Robertson Date of Verification 15th June 1906

I have to report that the Freeboard from the centre of disc to the top of the
 ry deck line, and the lines in connection therewith, as given below, assigned
 Committee to this vessel, have been correctly marked on the vessel's sides,
 accordance with the printed instructions:—

Centre of disc to top of statutory deck line	0 ft. 6 1/2 ins.
Centre of disc to top of statutory deck line at awning or part-awning deck	✓ ft. ins.
Fresh water line above centre of disc	3 ins.
Indian Summer line above centre of disc	✓ ins.
Winter line below centre of disc	1 1/2 ins.
Winter North Atlantic line below centre of disc	✓ ins.
Distance between the top of statutory deck line on vessel's side and the intersec- tion of the continuation of upper side of wood or iron deck with the vessel's side	at main, spar or upper dk. 1 ins. at awning or pt.-awning dk. ✓ ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

R. M. Wright Surveyor.

(To be filled up in London Office.)

Document No. 16883 Date of Committee's Minute 30.4.06
 Depth for record 12 ft. 3 ins.
 Boards compared and found correct by J. R. B. date 18.6.06
 Fee paid? Yes Form for Certificate A
 Instructions Write Certificate & Post date 18 JUN. 1906
 Certificate written 18 JUN. 1906 Noted for posting

W465-0101

© 2019

Lloyd's Register
 Foundation

19

THE UNIVERSITY OF CHICAGO

© 2019
Lloyd's Register
Foundation

17/2

100

3

7

1

[illegible]

Handwritten signature: *Handwritten signature*

[Faint bleed-through from the reverse side of the page]

MSW