

BERGENSKE (LONDON) LTD.,

DIRECTORS:  
J.H.L. NORWEGIAN. P.D. BOTTERELL C.B.E. BRITISH.  
H.K. LEHMKUHL, NORWEGIAN.  
THE S. FALCK, NORWEGIAN.  
KNUD SÖMME, NORWEGIAN  
(MANAGING DIRECTOR.)

TELEGRAMS: (INLAND) BERGENSKE, STOCK, LONDON.  
" (FOREIGN) BERGENSKE, LONDON.  
CODES: A.B.C. SCOTT'S, WATKINS, WESTERN UNION, BOE'S.  
TELEPHONE: AVENUE 6654 (5 LINES)  
" 7627 (10 LINES)

33/35, ST MARY AXE,  
LONDON, E.C.3.



12th November 1934.

The Secretary,  
Lloyds Register,  
71 Fenchurch Street,  
E.C.3.

Dear Sir,

S/S "BOMARSUND"

This vessel as you know, is lying at Antwerp damaged, and I shall be much obliged if you will kindly give Messrs. Bergenske (London) Ltd. any information as to the extent of the damage, and what would be required in order for her to obtain a seaworthy certificate for towing to the U.K.

Thanking you,

I am,

yours faithfully,



© 2020

Lloyd's Register  
Foundation

W466-0200

Referred to the Chief Ship Surveyor

*EO*

13 NOV 1934

also for Mr. Spinks to note.  
Also for Mr. Carey to note.

*The Rep. from Messrs. [unclear] who presented this information that it wd. be necessary for the outstanding fees to be paid before any information could be given*  
*EO*  
*13-11-34*

LONDON E.C.3  
25.32  
EXAMINATION  
[Faint stamps and text]



© 2020

Lloyd's Register  
Foundation

Lloyd's

SPILL  
Steam  
fog in  
Easton  
men

Lloyd's

Follow  
Station  
steamer  
At 4 30  
two. It  
tone. 2

Follow  
Station  
Spanish  
Pan, G  
W. at  
danger  
end, o  
" Tallin

Follow  
Station  
BOMAR  
G.M.T.  
No assi

leakage  
lost. M

STELLA

BOMAR