

under Upper Deck
Break
HOUSE
288.40
4.68
House on Bridge

Depth, at middle of length from top of keel to top of upper deck beams at side.....

21.75

Built at Bill Quay

TELEPHONE NOS 2 41 & 2242. CENTRAL.

THE STEAMSHIP COMPANY LIMITED.

Address, NEWCASTLE.

Milburn House
Newcastle on Tyne 10th April, 1916.

Messrs. Wood, Skinner & Co., Ltd.,
Bill Quay-on-Tyne.

Sirs,

"Nos. 204 & 205 Ships".

With reference to the above new steamers which you are to build for us, please note that we wish to dispense with the Bulkhead Fore Hold, as per Lloyd's Rules, making four Watertight Bulkheads, and compensation to be fitted in lieu of same, in accordance with Lloyd's requirements and we shall be glad if you will arrange accordingly.

Yours faithfully,

THE FIRE BRUNETT STEAMSHIP CO. LIMITED.

J. W. Bruner

MANAGING DIRECTOR



Lloyd's Register Foundation

W467-0206

Height of Outside Brackets above at bilge	36	FORE	36	Deck	Wood Deck. Material & thickness
BR BOTTOM PLATING breadth and	42x50				

1917
No
met
to be entered
see
to
float, or
Feet. Inch
19 3
Bridge
Upper
nd spac
"
"
"
ERS.
late above
ostal Plat
length.
length
h Angle
length
h Angle
length
Angle...
thickness
of Bridge
thickness
of Bridge
(Bridge)
with
always...
with
ge)
ridge)
& thickne
with

