

End by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

31 DEC 1935

2E

VESSEL'S NAME

Antónios Kondissis

Rpt.

Pir.

No. 4139

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Excerpt from Sub-Committee's Report, 24/5/32.

Date of Survey

COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S.~~ No.

This Survey, due

9.35

now

held

now

completed, and the following repairs carried out (due to wear & tear):-


Elec. welding repairs effected front end plating in both bilges. also to  
Comb. chr plating funnels. & minor repairs effected to stays

It is submitted the vessel is eligible to remain as classed, with  
notation of

B.D. 12.35

S. 12.35

as recommended.



© 2019

Lloyd's Register

Foundation

31.12.35

W468-0216