

Lap of plating 44 Per centage of strength of joint Rivets 70.5 Working pressure of shell by rules 100 Thickness  
Plates 69.7 13/16" 8 thick  
Radius of do. 5'-9" No. of Stays to do. 6 Dia. of stays 1.59" Diameter of furnace Top 5'-5 1/2" Bottom 5'-1"

"Cabo Cullera" Mdb. Rpt. No 5719.

It is submitted, that a copy of this report be forwarded to the Surveyors at Bilbao for their guidance in fitting it on board, & they should be requested to report the same & fill in particulars omitted from the report, on completion.

ARK J.W.D.  
20/3/09  
20.3.09

For Mr. J.A. Still  
to note same Bbs. L24/3/09

22.3.09



© 2019

Lloyd's Register  
Foundation

N 469-0333