

M. Wood

27376

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Bbo.

When received in London Office

Name

Alfonso Perez

No.

No. in Reg. Book

Registry (For Foreign Vessels)

Santander

Steel

Steel

State whether Classed by Lloyd's Register

Yes

Owners

Date of Verification

I have to report that the Freeboard from the centre of disc to the top of the deck line, and the lines in connection therewith, as given below, assigned committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

Centre of disc to top of statutory deck line *5* ft. *11 1/2* ins.

Centre of disc to top of statutory deck line } *—* ft. *—* ins.
at awning or part-awning deck . . . }

Fresh Water line above centre of disc . . . *6* ins.

Indian Summer line above centre of disc . . . *5 1/2* ins.

Winter line below centre of disc . . . *5* ins.

Winter North Atlantic line below centre of disc *✓* ins.

Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of ~~wood~~ steel deck with the vessel's side } at ~~main, spar or upper dk.~~ *13 1/4* ins.

at ~~awning or pt.-awning dk.~~ *—* ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or steel deck.

Certs & Bbo.

M. Wood

Surveyor.

(Filled up in London Office.)

At No.

Date of Committee's Minute

For record } Moulded Depth . . . ft. ins.
Register Book. } Freeboard . . . ft. ins.
Corresponding Draught . . . ft. ins.

Reads compared and found correct by

Date

aid ?

Form for Certificate

A. J. Carr


ons

Date

te written

6.11.24

Noted for posting



Lloyd's Register Foundation

6500-165M