


Lloyds.
H/MAB.

TELEGRAPHIC ADDRESS: "WEIRCO" ALD, LONDON.

TELEPHONES: AVENUE { 8974
8975
4970 (4 LINES).

NEW WEIR & CO

M. WEIR.	D. WEIR.
J. R. BROWN.	A. L. WEIR.
J. NIVEN.	



BALTIC EXCHANGE BUILDINGS,

21 BURY STREET

LONDON, E. C. 3.

12th April, 1932.

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch St.,
E.C.

Dear Sir,

S.S. "LINDENBANK".

We are pleased to learn from our Superintendent that your surveyor at Avonmouth has re-measured the above vessel. We would be glad to learn from you at your earliest what work is necessary to carry out to comply with the new load line requirements. The vessel leaves Avonmouth tomorrow for Antwerp to complete discharge, and will probably drydock there, and we should like to put this work in hand. You might also please advise us what extra immersion is allowable, and when it will be in order to have the new markings cut in, and where it can be done.

Thanking you in anticipation of an early reply.

Yours faithfully,

© 2019

Lloyd's Register
Foundation

W473 - 0307

Referred to the Chief Ship Surveyor.
(Freeboard).

12 APR 1932

Early reply
Requested



© 2019

Lloyd's Register
Foundation