

26 APR 1935

COPY.

Lloyd's Register of Shipping.



Port BAHIA BLANCA

2nd APRIL 1935.-

This is to Certify *that I have*

surveyed the S.S. "OINOUSIOS" 3716 TONS NET

REGISTER OF CHIOS FOR REPAIRS TO STEEL PLATE BRACKET
CARRYING PORT SIDE STEERING CHAIN GUIDE PULLEY.-----

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and


that I have Recommended that she be CONTINUED AS CLASSED
IN THE REGISTER BOOK.-----

(S) being fit to carry A DRY AND PERISHABLE CARGO.-----

H Bruce

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

W476-0081