

3 plans under separate cover.

Lloyd's Register of Shipping,

3, Steinhoeft,

Hamburg, 26th August, 1931.



Dear Sir,

I am submitting under separate cover duplicate copies of a plan showing a proposal for replacing the upper part of the sternframe of the s.s. "ELSA MENZEL" which vessel is at present at this Port undergoing repairs. With the plans a further sketch is enclosed which embodies a proposed arrangement for making a temporary repair to the broken sternframe. The sketch is forwarded in order that it may be clearly seen where the fracture has taken place. The rivets in the upper scarph have not yet been removed and the full extent of the fracture cannot be seen but from the examination made the extent is approximately as indicated in red on the sketch. In order to avoid the very serious expense of renewing the broken part of the sternframe, including the propeller boss, the proposal submitted shows an arrangement for providing a new scarph above the propeller boss. Full particulars of the form of construction proposed at the scarph are given on the plan. The Owners desire that if this arrangement is approved it should also be regarded as a permanent repair.



© 2019

Lloyd's Register
W482-0041/2
Foundation

The favour of a reply at your earliest possible convenience, preferably by cablegram, is requested.

I am, Dear Sir,

Yours faithfully

for A. Chisholm

Rooster

The Secretary,

LONDON

Lloyd's Register
- 0042-2/2

Referred to the Chief Ship Surveyor.

Ep
URGENT
Reg cable reply by wire
27 AUG 1931
28 W inst.

Stamp

RECEIVED

Handwritten signature

RECEIVED

I am, Dear Sir,

in reference to the ...
... to ...

...
...
...

Sub. Plan
the ...

LONDON



© 2019

Lloyd's Register

Report

The Vessel has ...