

Received from Chief Surveyors

30 OCT 1929

Steel S.S. "INCHDAIRNIE". Report Jck. No. 682

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case. The Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

No. 2 SURVEY PARTLY HELD.

29 When proposed to be completed

etc.

The S.S. No.2, due 5,29, was partly held at Rotterdam in May last by the examination of the bottom and rudder in dry dock, of all double bottom tanks and fore and after peak tanks and examination of the windlass.

The Antwerp Surveyors reported in March last that the steering cylinders had been renewed and the telemotor gear overhauled.

In April the vessel lost her rudder and sustained damage at sea.

The new Owners now state that the vessel is under repair at ^{the latter Owners' pleasure 1-11-29} and request to be informed of what part of the survey has been carried out.

It is submitted the Owners and Jacksonville Surveyor be informed as above.

[Signature]

W. M. A.
30.10.29.



© 2019

Lloyd's Register
Foundation