

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

1st January, 1923.

Dear Sirs,

I am in receipt of your letter of the 29th ultimo relative to the steamer "KINGHORN", and in reply I have to say that the repairs referred to in the Special Reasons List have already been dealt with, but a report has now come to hand from the Society's Surveyors at Baltimore from which it appears that on account of damage a new propeller has been fitted but the Surveyors recommend that the stern tube fitting in the sternpost should be examined at the next drydocking.

I am, Dear Sirs,

Yours faithfully,

Assistant to the Secretary.

The Surveyors,

ROTTERDAM.



© 2019

Lloyd's Register
Foundation

W482-0484