

Surveyors 3. 51.21

Received from Chief Surveyors

2-JUN-1921

NAME Steel S.S. "BULGARIAN". Report Lon. No 84015

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.



On cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — *Extract from Sub-Committee's Report, 24/5/02.*

Survey General Examination When due 5.21

Notation of Lon.11.20 has been made in this case.

The London Surveyors now state they are informed by the Owners' Representative the vessel will be placed in dry dock on her return from the present voyage for further examination.

It is submitted action be deferred.



1. 6. 21.

W486-0241



© 2019

Lloyd's Register
Foundation