

M Wood

29462

FREEBOARD VERIFICATION FORM FOR STEAMERS.

London.

When received in London Office 6 MAR 1922

Name S S Bulgawan
 No. 143434 No. in Reg. Book 10971 Supp. 36535
 of Registry (For Foreign Vessels)
 or Steel Steel State whether Classed by Lloyd's Register YLS
 of Owners Hester & Laurant Ltd Date of Verification 4th March 1922

I have to report that the Freeboard from the centre of disc to the top of the dry deck line, and the lines in connection therewith, as given below, assigned to this Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	2	ft.	5 1/2	ins.
From centre of disc to top of statutory deck line at awning or part-awning deck	✓	ft.	✓	ins.
Fresh Water line above centre of disc			5	ins.
Indian Summer line above centre of disc			3 1/2	ins.
Winter line below centre of disc			3	ins.
Winter North Atlantic line below centre of disc			5	ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side				
			at main, spar or upper dk.	1 3/4 ins.
			at awning or pt. awning dk.	— ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

Excess in excess of requirements has now been fitted to the hudge

James D. English Surveyor.

(To be filled up in London Office.)

Document No. 29462 Date of Committee's Minute 2. 11. 20

Particulars for record in Register Book.	Moulded Depth	21	ft.	7	ins.
	Freeboard	2	ft.	5 1/2	ins.
	Corresponding Draught	19	ft.	5	ins.


Boards compared and found correct by W.D. Date 6.3.22

Fee paid? _____ Form for Certificate A

Particulars _____ Date _____

Certificate written 7.3.22 Noted for posting John

W486-0295



© 2019

Lloyd's Register Foundation

the
asked to
will of the
firming to
backhand.
M.W.
6.3.22



© 2019

Lloyd's Register
Foundation