

WRECK BOOK No. 154

9658

# REPORT OF TOTAL LOSS, CASUALTY, &C.

No. 04975 in R. B. Wreck Book, p. 66/39

Date of writing this report 26th October 1939

Vessel's Name *Steel Sm. Trawler "Arlita"* of *Fleetwood* Tons {Gross 326 Net 134

Built at *Selby* When *1916* 2 Casualty notice sent to Owner *10/10/39* Owner's reply *23/10/39*

Owner's Name *J. Mearns & Son, Ltd.*

Address *Dock Street, Fleetwood.*

RETAIN

SOURCE OF INFORMATION

Case previously before Date Last Minute  
Classing Committee.

Particulars of Classification.	
<i>F100A1</i>	
<i>Stm Trawler</i>	<i>FLMC 7.36</i>
<i>5.39</i>	
<i>ss. No 3-4.28</i>	<i>BS 5.39</i>
<i>ss. No 2-3</i>	<i>TS 4.39CL</i>

Two trawlers—the Lord Minto and the Arlita—are reported to have been sunk and their crews rescued by another trawler. The Lord Minto (295 tons) was built in 1914, and the Arlita (326 tons) in 1916. Both were registered at Fleetwood.

Times 20/9

Date of Casualty *18th September, 1939*

of particulars of Casualty This vessel is reported to have been sunk by submarine off St. Kilda on the 18th September, 1939.

The Owners concur.

Registered Record

*Sunk*

Date of Committee *FRI. 27 OCT 1939*

Committee's Minute

*Sunk*

*Write Hoyle*



© 2021 Lloyd's Register Foundation

W489-0180

*B.S. 5.39. T.S. 4.39.*