

S.S. "Lord Mersey."


Hull. Rpt 29/55.

It is submitted that the Hull Surveyors should be requested to state whether they are correct in reporting that two screw stays are fitted to each combustion chamber girder, in view that three are shown on the boiler plan.

JWD.  
28/2/16

JM

The boiler plan to be returned for duplicate boiler.  
as requested.



© 2021

Lloyd's Register  
Foundation

W489-0189