



Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 20th September, 1940.

Dear Sir,

In reply to the enquiry contained in your letter of the 16th instant regarding the Electrical Installation of the steamer "MALRIX", our report No. 50834, we have to report that the installation was examined, the dynamo overhauled, cleaned and varnished and the entire system tested in accordance with the Rule and found satisfactory.

It is regretted that owing to an oversight this information was omitted from the above report.

The recommendations contained in our report, therefore, should read: BS 8,40 and RLMC 9,39 as previously recommended.

We are, Dear Sir,

Yours faithfully,

The Surveyors,

Per:-

The Secretary,
WOKINGHAM.

It is submitted that
this vessel is eligible for
THE RECORD.

Lloyd's Register
Foundation

W49-0094

23 SEP 1940

Kur

H
RS

The following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

the following are

© 2020

Lloyd's Register
Foundation

