

S.S. "CHARLBURY".

It is submitted the Owners be informed that from information received from the Society's Surveyors at Barry, it would appear that in order to comply with the requirements of the International Loadline Convention, the following will require to be done:-

- (1) Hatchway beam on No.3 hatchway on superstructure deck should be made equal to the requirements of the Rules.
- (2) The covers of the escape hatchways in the tween decks in way of No.3 hatchway ^{Should} ~~being~~ secured, to the Surveyors' satisfaction.

They should also be informed that particulars of the Freeboards which could be assigned under the Convention will be forwarded to them immediately in receipt of information regarding ^{the} ~~displacements~~, which is being obtained from the Builders.

The Barry Surveyors should be advised.

S.T.B. *Reyn.*

19. 3. 32.

To Owners + Barry Surveyors.

21/3/32.



© 2020

Lloyd's Register
Foundation

W490-0047