

s/o "Carnarvonshire"

Bil. Rpt 7346

It is submitted the Belfast Surveyors should be informed that it is concluded the screw shaft tunnel is watertight but as this is not definitely stated on their report they should confirm this.

17/3/14.

JW2
16/3/14

ARR

Lloyd's Register
W4900-0094