

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME Street S.S. "WYNSTONE" Rpt. hon. No. 83777

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Remarks of Survey

First Entry

Before this case receives consideration the Surveyors should be requested to state:-


If frames in way of Raised Quarter Deck are ordinary or bulb angles.
Height of filge brackets.

Is Raised Quarter Deck stringer plate .50" abreast openings as approved.
size of forecastle deck stringer angle.

Are rivets in edges of sheerstrake & keel $\frac{7}{8}$ " diameter as approved
or $\frac{3}{4}$ " diameter as in report.

Dr. 9-12-20.

no entry
13/12/20



© 2020

Lloyd's Register
Foundation

W 491-0101