

1

Sent to Chief Surveyors

12.1.39

Received from Chief Surveyors

13 JAN 1939

VESSEL'S NAME

Stl.Sc. "ALADDIN"

Report

N.Yk.

No.

37952

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

2nd S.S.No.1  
BS

When due

12,37  
10,38

The class is subject to indented bottom plating being dealt with.

The 2nd S.S.No.1 became due 12,37.

Action has been deferred from time to time on account of the vessel being laid up.

When the case last received consideration on the 23rd ultimo, the vessel being still laid up, the Owners were asked to furnish the usual undertaking.

In reply the Owners' London Agents now write that they are now advised by the Owners that the vessel has been sold for scrap.

The year of grace expired at the end of last month.

It is submitted a record of "To be broken up" might now be made in the Register Book.

*[Handwritten signatures and date]*  
13.1.39



© 2020

Lloyd's Register  
Foundation

WF12-10145