

The 2nd SS 7701 will become due 12-37

of Surveyors 27-10-37

Received from Chief Surveyors

NAME ALADDIN

Report N.Yk

No. 37952

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Survey Condition When due

N.Yk. 35007

Subject to indented bottom plating being dealt with.

Author
2-11-37

O.L. = 453'-0"



© 2020

Lloyd's Register
Foundation

W492-0165