

COPY.

Lloyd's Register of Shipping.



Port OF RANGOON,

28th June 1937.

This is to Certify that I have had

Surveyed the S.S. "Aungban" of Rangoon, No. 71063 in the Register Book, by a competent Engineer Surveyor in consequence of repairs to windlass gypsies

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by ^{him} me have been completed to ^{his} my satisfaction, and that I have **Recommended** that she be continued as at present classed without fresh record of survey, she

being fit to carry petroleum in bulk.


Survey Fee Rs. 36/-

R. P. Taylor

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

W492-0266