

COPY.

Lloyd's Register of Shipping.



Port of BREMEN.

17th October, 1936.

This is to Certify that I have

Surveyed the Steel Ss. Steamer "AFRIKA", 8407 tons gross of
Emden afloat at Emden for Condition after encountering heavy
weather during the voyage from Narvik to Emden on the 16th
and 17th September, 1936, and damage repairs xxxxxxxxxxxxxxxx
and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, ~~stating that all repairs~~
~~recommended by me have been completed to my satisfaction.~~ and
that I have **Recommended** that she be eligible in my opinion
to remain as classed in the Society's Register Book without fresh
record of Survey subject to starboard middle side stringer in hold
No.1 being fitted as made on Port side after vessel's returning
from her present voyage to Narvik,
being fit to carry dry and perishable Cargoes. xxxxxxxxxxxxxxxx

xx

A. Holte.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."