

4m, 8, 12

Disclass 2B

Received by Chief Ship Surveyor

9/12/12

Received from Chief Ship Surveyor

VESSEL'S NAME

Stt St Australia

Rpt.

Hamb

No.

12072

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

It is submitted the Hamburg Survey should be requested to state by wire whether the frames fitted in No 1-2+4 holds are 9x3 1/2 x 5/8 or 9 1/2 x 3 1/2 x 5/8 as approved.

Mr. Hamburg  
107 17/12

Mr.

R/811

10/12/12



© 2019

Lloyd's Register  
Foundation

W497-0191



OK 108

CONTINUED PREVIOUS PAGE 108

THESE ARE THE ONLY TWO COPIES OF THIS DOCUMENT AND ARE NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM.

RETAIN



© 2019  
Lloyd's Register  
Foundation