

Lloyd's Register of Shipping,

Midland Bank Chambers,

Newport, Mon. 1st April, 1925.

Dear Mr. Watt,

With reference to my freeboard report No. 21312 on the steamer "AUSTRALIA", submitted yesterday, I regret that I made an error in the freeing-port area, and shall be much obliged if you will kindly have my report corrected accordingly. The report should read:-

Area of freeing ports required by Para 11 (e) each side of vessel =	9.5 sq. ft.
Freeing ports (each side of vessel) =	<u>11.2 " "</u>
Total excess	<u>1.7 " "</u>

With kind regards,

Yours sincerely,

St. Bryden

Watt, Esq.,

LONDON.



© 2019

Lloyd's Register
Foundation

W197-0246

