

28 NOV 1920

Chief Surveyors 29-11-20

Received from Chief Surveyors

NAME SH. SS. Sonnenfels Report Bmr. No. 430.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Survey

When due

The writers should be informed that the Anchors & Chain cables require to be in accordance with, or equivalent to letter A table 31.

If the Anchors & Chain cables are examined & verified with certificates, found ^{or placed} in order & tested as required the figure 1 will be assigned.

elg

to lengthen: 29.11.20

also

M. Cassin

to wire hps: 29.11.20



2020
Lloyd's Register
Foundation