

TONNE
Less
Tonnage

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

ENCLOSURES.

4th May 1911.

Sir,

With reference to your First Entry Machinery Report No. 30020 in the case of the S.S. "HAVILDAR" I have to point out that the size of screw shaft as per Rule is 14.8" and not 14.26" as stated on Report, and also that the letter for Record of boilers is (r) and not A as placed on the Report, the longitudinal stays in steam space being of steel.

At the same time I return herewith as desired the approved boiler plans for the Surveyors guidance in dealing with duplicate cases.

I am, Sir,

Your obedient Servant,

Secretary.

The Secretary,

GLASGOW.



© 2019

Lloyd's Register
Foundation

W501-0239