

COPY.

12 JAN 1949

Lloyd's Register of Shipping.



Port Aruba, N.W.I.

20th October, 1948

This is to Certify *that I have*

*Surveyed the S.S. "MATURINOS" 5500 tons gross of Guiria, whilst
afloat in San Nicolaas Harbour, Aruba, N.W.I. on the 18th October,
1948 and subsequently, on account of repairs.*

*and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all ^{temporary} repairs
recommended by me have been completed to my satisfaction, and
that I have **Recommended** that she ~~be~~ continued as classed, without
fresh record of survey, subject to shell bottom plates in way
main tanks Nos 2 and 4 port and side plate No. 7 in 2nd below
main sheer starboard side being specially examined and repaired
at first opportunity.
being fit to carry Petroleum in bulk.*


W. S. Holmes

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
ever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of
of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

B.) 5M-3-48

PRINTED
IN
U.S.A.



Lloyd's Register
Foundation