

20001 1047

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"SRDJ"

Rpt.

Spt.

No. 648

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

It is submitted before this case receives the consideration of the Committee, The Split Surveyor be requested to refer to Split report No.557 in which it stated that the shrouds and stays, found to be somewhat rustbound, were recommended to be renewed, and to state whether this recommendation has been carried out.

*JS*  
19.10.37  
*JD*



© 2020

Lloyd's Register  
Foundation

W503-0062



RETAIN



© 2020

Lloyd's Register  
Foundation

REPAIRS, OR

PRIMARY OF D

Renewed

Removed a

Paired or P

PRESENT COND

els

illing of Deck

amings

ams & Fasteni

tside Plating ...

" " In W

earthbooks

rooms

ams

Yare Frames

ngitudinals

ubverres

ats

elbons

ingers

ter Bottom Pla

General

St

this sury

survey, 1