

LLOYD'S REGISTER OF SHIPPING,

425 KING STREET

JACKSONVILLE, FLA.

27th February 1920.

LLOYD'S REGISTER
NEW YORK

REC'D MAR - 1 1920

ANS'D

Secy.,
New York.

Sir:-

Yours of the 16th inst. received relative to
steamer "JACKSONVILLE" Jax. Report No 139.

The transverse frames and beams in way of the after
peak are as approved. The butts of shell plating in way of
ridge side and butts of sheerstrake and strake below clear
of the bridge is as required.

The hold transverse lugs to shell are double throughout
or three spaces above tank top.

Yours very truly,

J. Hugh Boyle

S. I understand this vessel is now repairing at Newport News
having lost her rudder and broken the sternframe. This
probably happened in Jax where the vessel was aground on
several occasions and loaded on the bottom.



© 2020

Lloyd's Register
Foundation

WS05-0198