

COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping.



Port BILBAO.

31st August, 1923.

This is to Certify that I have

Surveyed the Boiler and Machinery of the twin screw steamer

"CRISTOBAL COLON" 10,137 tons gross register of Barcelona

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the record of A L.M.C. 8-23. Subject to starboard propeller being renewed at Owner's convenience.

be made in the Register Book in the case of this vessel.

Y. Thomas Miller

Engineer Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or entry published by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

Certificate has been issued in the Spanish language on the reverse side of the original.

COPY FOR LONDON OFFICE

Lloyd's Register of Shipping



Port BILBAO

21st August, 1935.

This is to Certify that I have

Surveyed the Boiler and Machinery of the twin screw steamer

"CRISTOBAL COLON" 10,137 tons gross register of Barcelona

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

recommended that the record of L.R.C. 8-35, subject to

starboard propeller being renewed at owner's convenience.

be made in the Register Book in the case of this vessel.

The above recommendations were made to me on the

W. J. ...

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or for any error in the Register Book or other publication of the Society, or for any error of the press, or for any error of the Surveyors, or other Officers or Agents of the Society."

L.R.C. - This Certificate has been issued in the Spanish language on the reverse side of the original.

© 2020 Lloyd's Register Foundation

W 2000/100