

21 AUG 1937

11

Received from Chief Ship Surveyor

ed by Chief Ship Surveyor

SEL'S NAME

Lemberg

Rpt.

Hfx

No.

2807

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


ure of Survey

Dorking

The *Halifax N.S* Surveyor's reports this vessel placed in dry dock, bottom cleaned and coated, repairs to *shell plating, rigging* and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey *7.37* as recommended.

100 R1  
*Stm Hawker*  
*7.37 Hfx.*



© 2020

Lloyd's Register  
Foundation

WS07-0043