

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

Enclosure

31st March, 1913.

Gentlemen,

I am in receipt of your letter of the 28th instant respecting the completion of the survey of the hull of the new steamer "COLUSA".

It appeared that in order to complete the survey of the machinery, the safety valves require to be adjusted under steam, and the engines tried under steam, which is to be done early on Wednesday next.

In the circumstances the First Entry Certificate for the hull of the vessel is enclosed herewith, but must not be handed over until the survey of the machinery has been satisfactorily completed, and you should therefore be careful to be guided accordingly.

I am, Gentlemen,

Your obedient Servant,

The Surveyors,
GREENOCK

Secretary.



© 2020

Lloyd's Register
Foundation

W508-0032

83.

-003

Diameter at smallest part 9.62 Area supported by each stay 450 Working pressure by rules 240 Material of 1
"15" Greatest pitch of stays 11 1/2" Working