

# Lloyd's Register of Shipping.

2500, 12, 19.

to Chief Surveyors.

Received from Chief Surveyors

VESSEL'S NAME *Stel S.S. "MACEDONIER"*

Report *Go*

No. *40992*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.32.)

ture of Survey

When due

✱ 100-A-1. (Stel)

2 Dks (Stel)

Cell DB 342' 920t, DTA 30' 850t, FPT 121', APT 104t

FK, "Intermediate Tween dk BH in After Hold Dispensed With - 5 BH to upper Dk  
1 BH to 2<sup>nd</sup> Dk only" Cew, Ply as A.C.P., P 37', B 120', F 45'



© 2021


Lloyd's Register  
Foundation

W 51-0227

See letter from Thomas re  
Mission of Turen deck hullhouse  
attached to last entry report  
in SS-Olympia

Report

SELF'S NAME 2-2-2 Macedonia



© 2021

Lloyd's Register  
Foundation