

8

Steel Screw Steamer "OAKMERE", Sunderland S.B.Co's No.259.

The total weight of the three stockless bower anchors supplied to this vessel is 60 lbs. in excess of that required by the Rules.

In the case of the 1st. bower anchor, the head is 12 lbs., or $\frac{1}{2}$ of 1%, less in weight than required, but the total weight of the anchor is 98 lbs. in excess of the rule requirements.

In the case of the 2nd. bower anchor, the head is 39 lbs., or about 2%, less in weight than required, but the total weight of the anchor is 222 lbs. in excess of that required by the Rules for 2nd. bower anchors.

The case received the consideration of the Classing Committee on the 15th instant, when it was decided to approve of the anchors, subject to the Owners' consent being obtained. It was further decided to report the case to the General Committee.

The case is accordingly submitted for the information of the Committee.

RBA
20/7/10

E. L. L.


General Committee,
Thursday, 21st July, 1910.

Classing Committee's decision
confirmed

3. 7. 10

22: 21.8%

work returned



Lloyd's Register
Foundation

WS10-0190