

Inspected by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME "THORPEHAVEN".

Rpt. Msl.

No. 9558.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

 Name of Vessel COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND~~ BOILERS FOR ~~S-S~~ No.


This Survey, due 2,38 ^{now} partly held 4,38 now
 completed, and the following repairs carried out (due to wear and tear):-

2 screw stays renewed.

It is submitted the vessel is eligible to remain as classed, with
 notation of BS 4,38 as recommended.

WS10-0342

7.6.38.



© 2020

Lloyd's Register
Foundation