

Sld 19/12/32.

ESSEX JUDGE

8746

(Received at London Office

15 SEP 1924

Hd. 22456

No. 8746

REPORT of SURVEY for REPAIRS, &c.

ing Report 11-9-24 when handed in at Local Office 11-9-24 Port of Genoa

Survey held at Spezia Date, First Survey & Last Survey 9-9-1924

on the Wood, Iron or Steel & "Alberto Fassio" Master

INAGE:- Built at Sunderland By whom Short Bros Ltd. When 1912 8

Owners Villain & Fazio Port belonging to Genoa

Owners' Address (if not already recorded in Appendix to Register Book).

ed Afloat or in Dry Dock? yes Name of Dock Armada Dry Dock Destined Voyage

ell DBor DBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted

apacity tons. FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements).

all alterations in the existing records should be underlined.

he Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside

be examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,

and of the inner bottom plating, especially in the boiler space.

Report, No. Port

Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the

pairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs

of Damage (the cause of which must be stated) should be separated from Repairs due to other causes;

being detailed in the body of the report, should be summarised in the form shown below. Whenever the

of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on

this form. State also the dates and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why

declined? Was a damage report made by anyone else? If so, by whom?

EXAMINATION AS PER RULE, FOR Verification of the free-board.

done. This vessel is at Spezia under special survey No 3 and

have damage repairs, as per our Rpts 8650 & 8706. The survey

are almost completed and it is expected that the vessel is

to sail again at the end of this month. The markings of the

on the vessel's sides have been verified and found in order as

Rpt 12 attached.

Signed S. W. B.

15.9.24.

MAJOR REPAIRS:-

Plates. Frames. R. Frames. Floors. Beams. Str. Plates. Dk. Plates. Other Items:-

Pair or Repaired

repaired in place

ION OF THE

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt (State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Dblng. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking ditto

Treenails ditto

Breasthooks & Stemson ditto

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting ditto

(State if examined.)

Copper, or Y.M. of Wood Vessels (State if on Fell.)

When put on, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if new ranged)

length size

Rule length size

Hawser & Warps

Standing & Running Rigging

Observations, Opinion as to Class, Recommendation, &c.:-

clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon

thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of

"or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptnd15, &c."

is forwarded for information of the Committee.

Fees applied for,

Repair Fee (if any)

(if chargeable)

(if any)

Received by me,

Surveyor to Lloyd's Register of Shipping.

tee's Minute

er Assigned

MARKING FORM

RECEIVED 30 DEC 1927

WS10-0376

Lloyd's Register Foundation