

Lloyd's Register of Shipping.

MERCHANT SHIPPING (SAFETY AND LOAD LINE
CONVENTIONS) ACT, 1932.RENEWAL SURVEY IN ACCORDANCE WITH
SECTION 48 (4) OF THE ABOVE ACT.(Port) *Newcastle-on-Tyne.*
(Date) *17th June 1937*

I have to report that I have surveyed the

S.S. PEGAWAY of *NEWCASTLE* O.N. *148867*

on this date.

I have compared the arrangements on board the ship with those given in the original freeboard report and I have found them to be in agreement therewith or equivalent thereto, and the whole to be in efficient condition.

The special Survey N° 3 has been carried out in its entirety at this time and the record of Survey 6,37 with notation S.S. South Shields N° 3 - 6,37 recommended. The following repairs have been effected:-

- 35 hatch cleats and 90 hatches (50 single 10 double) renewed.*
- Hatch locking bars replaced throughout with new wire lashings.*
- 1 Port-light renewed.*
- 3 Ventilators and one ventilator crowning tube renewed.*
- Poop store hatch rest bars renewed.*
- 2 new Kaysanlin's supplied for bunker hatch.*
- 9 Hatch beams renewed, and 3 repaired.*

The freeboard marking has been verified and found to agree with the freeboards given on certificate No. *5000* dated *8th August 1933* which is returned herewith.

A. V. Champness.

Surveyor to Lloyd's Register.



Is fee paid

Fee *£ 3-0-0*

Verification form already forwarded.

© 2020

Lloyd's Register
Foundation