

2m. 11.29.

FREEBOARD REPORT on the

"Y. S. S. "Gardenza".


It is submitted the Bremen Surveyors be requested to check the moulded depth given on their freeboard report as 7.94', as the depth given on the approved midship section is 8.35'. They should also give the length on the load water line, the thickness of the sheathing on the upper deck, full particulars of the freeing ports, and the distance from the top of the keel to the lower edge of the lowest side scuttle if fitted. Scuttles are fitted.

Hamburg Surveyors should also be advised.

[Signature]

E. W. B.

16-7-31.



© 2020

WS12-0090

Lloyd's Register
Foundation