

NO RESPONSIBILITY WILL BE ACKNOWLEDGED FOR ANY CONSEQUENCES ARISING OUT OF STRIKES, LOCK-OUTS, COMBINATIONS OR OTHER LABOUR DISTURBANCES NOR FOR LOSS OR DELAY DUE TO HOLIDAYS, BAD WEATHER, FIRE, ACCIDENT OR ANY OTHER CAUSE BEYOND THE COMPANY'S CONTROL OFFERS FOR DRY DOCKING ARE SUBJECT TO DOCK BEING AT LIBERTY. ALL TRANSPORTING AT OWNERS RISK.

R. & H. GREEN AND SILLEY WEIR, LTD.

SHIP REPAIRERS & ENGINEERS.

TELEGRAMS:
REPAIRS, ALDOCK, LONDON

TELEPHONE NUMBERS:

GENERAL OFFICES: ALBERT DOCK 2121 (5 LINES)



Works:

LACKWALL YARD, EAST 4171 & 4172 | SURREY DOCKS, BERMONDSEY 3187 & 3188
ROYAL ALBERT DOCK, ALBERT DOCK 1641 | MILLWALL DOCK, EAST 4611 & 4612
(3 LINES)
CENTRAL WORKS ROYAL ALBERT DOCK, | TILBURY DOCK, TILBURY 53 & 115.
ALBERT DOCK 1506

CITY OFFICE: 130-132, LEADENHALL STREET, E.C.3.
TELEPHONE AVENUE 8308 (3 LINES) TELEGRAMS: INTERKNIT, STOCK, LONDON.

Tilbury Dry Dock Works,
Tilbury,
ESSEX.

7th January 1935

OUR REF.

YOUR REF.

The Senior Surveyor,
Lloyds Register of Shipping,
71, Fenchurch Street, E.C.3.



Dear Sir,

S.S. "BELGENLAND"

Acting on instructions from Captain Rickcord of the Atlantic Transport Line and The Red Star Line, we have sent bearer, who with your kind permission will collect the Leadline Certificate for the above-named steamer, as this is required tomorrow for signing on.

Captain Rickcord will call at your office on Wednesday to collect the remaining two copies as it is requested that a total of three copies shall be supplied.

Thanking you in anticipation,

Yours faithfully,

for R. & H. GREEN AND SILLEY WEIR LTD.

J. London
Manager.



© 2020

Lloyd's Register
Foundation
w 512-0219

Referred to the Chief Ship Surveyor.
(Freeboard).

EO

8 - JAN 1935

W.S.

8.1.35

*Original Cert copy handed to Repres on 7.1.35
of Green's Survey made 7.1.35 - additional
copy to Capt. Rickwood 9.1.35.*



© 2020

Lloyd's Register
Foundation

TELEPHONES
ALBERT DOCK 1
TELEGRAMS:
TRANSLANTIC

The Lloyd's
71, 1
DON
1st
9th