

REPORT on the

"El. Paraguayo"

69887 R.B.


Owners London office phoned that freeboard certificates were lost and new certificates were required. Vessel is due at Liverpool on Thursday.

It is submitted the Liverpool office be advised and requested to verify the marking and forward the usual verification of marking form for the issue of new certificates.

*M. J.*

13.10.30

WS 14-0175



© 2020

Lloyd's Register  
Foundation