


# Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 10th February, 1938.



Dear Sir,

We have your letter of the 9th instant relating to the case of the S.S. "SANDGATE CASTLE", and our examination of the vessel in dry dock in May 1937.

The survey held upon that occasion was an ordinary docking survey, and no examination was made beyond those parts mentioned in our report No. 47850.

When in dry dock the opportunity was taken to examine generally Nos. 1 and 5 holds, but from that examination we had no occasion to make any recommendations for repairs.

Beyond the engine repairs noted in our report, we had no other survey to make in the machinery space, and the fuel bunkers were not examined.

We are, Dear Sir,

Yours faithfully,

The Surveyors,

Per:-

*John A. Mackintosh*

The Secretary,  
LONDON, E.C.3.

Referred to the Chief Ship Surveyor

M B

11 FEB 1938

Dear Sir:-

The engine room

of the ship

is now being

examined by the

Surveyor and the result will be reported to you.

Very truly yours,

Chief Ship Surveyor

London, E.C.2.

The Secretary

RECEIVED  
11 FEB 1938

© 2019

Lloyd's Register  
Foundation

Dear Sirs,  
I have the pleasure to inform you that the forthcoming issue of the Solicitor

