

COPY.

Casualty Rpt. W

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

25th July, 1938.

Dear Sirs,

S.

In reply to Mr. Bryan's enquiry over the telephone on the 19th instant respecting the case of the steamer "SANDGATE CASTLE", I beg to inform you that, as regards the position of settling tanks, somewhat similar arrangements are to be found on a number of recently constructed motor vessels in which the donkey boilers are situated immediately below tween deck oil fuel bunkers.

The arrangements were approved by this Society and so far have given satisfaction.

I am, Dear Sirs,

Yours faithfully,

Clerk to the
Classification Committee.

The Union Castle Mail Steamship Co., Ltd.,
Engineer's Office,
Orchard House,
BLACKWALL.



© 2019

Lloyd's Register
Foundation

WS16-0225