

For the information of Surveyors and the Committee only.

Received at



Lloyd's Register of Shipping

(Report on Vessel No. _____ Port Sunderland)

16886. SHIP FORGINGS ~~OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by John Rogerson & Co. Ltd of Walsingham for the Vessel No. 543, being built by Sir W. Hozford & Sons Ltd of _____ have been inspected by me as set forth below and found to be, so far as can be seen, Sound

New Sp. B.R. as Per Plan

Forgings or Castings.

Lloyd's


4208-N
W.C.

W. Campbell

Newcastle

	STERN FRAME.	RUDDER FRAME.	STEM.
...	<u>Cast Steel</u>	<u>Ingot Steel</u>	
...	<u>Cast</u>	<u>Forged & Machined</u>	
...	<u>10 1/2 x 9 x 8</u>	<u>12</u>	
Inspection ...	<u>Cast & Tested</u>	<u>Machined & Built</u>	
Inspected ...	<u>February 4, To September 5, 1919.</u>		
INGS.			
Standard Test			
ices.			
are inch	<u>34'8. 31'0.</u>	<u>29'6. 30'4. 30'8.</u>	
cent. 2.	<u>29% 30%.</u>	<u>29% 35% 35%.</u>	
Test—			
fracture	<u>120° 180°</u>	<u>180° 180° 180°</u>	
ground ...	<u>6 Feet.</u>		
Test—			
rding to Rules {	<u>Yes.</u>		
satisfactory ... }			

ETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.



(any chargeable) £ —

paid at

state whether scrap or puddled iron. If of steel, state whether made on the Open Hearth process.

WS2-0417

Messrs. W. M. Duxford & Sons

No 543

S.S. KOPANTON

Forging Certificate

SUNDERLAND RPT. NO. 27793



© 2019

Lloyd's Register
Foundation