

1

Sent to Chief Surveyors 10.7.12

Received from Chief Surveyors

VESSEL'S NAME Steelss Agnes Duncan Report Enk No. 16283

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Enly.

When due

* 100 A.1. (Steel)

1 SK. (Steel)

WB = Cell SB u SB 52' 185' 715' EPT 305' a.P.T 746.

FK. 2 Intermediate BH in main hold dispensed with 3 BH only. Cemi. Lloyd's ar. P. 71 F 38' Incl aft.

Enk
10.7.12

The Surveyors should be requested to state the thickness of the poop deck plating as this information has been omitted from their report.

Enk



© 2021

Lloyd's Register

W 521-0019