

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "TAVRIS".

Rpt. Nwc.

No. 95523.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Survey SPECIAL SURVEY OF ~~ENGINES AND/OR~~ BOILERS PARTLY HELD ~~FOR S-S~~ No.

~~LMC~~~~LMC(M)~~~~MS~~

BS

due 7,37, partly held

minor

~~now further advanced and the following repairs effected (due to~~

It is proposed to complete the survey at ~~Rotterdam~~.

at arrangements

It is submitted that ~~this proposal merits approval~~ and the vessel is eligible to remain as classed, and WILL BE eligible for the record

S 9,37


when the survey has been completed.

The following remains to be done to complete the Survey

~~Adjust safety valves.~~ *Some of the welded stay tubes to be removed for examination of the threads in the tube plate holes.*

Submitted the Owners be requested to have the survey completed with a little delay as possible

25.10.37.



© 2020

Lloyd's Register
Foundation
W525-0082

RETAIN



© 2020

Lloyd's Register
Foundation

in Donkey B
Cast Rep
Particul
Periodical Sur
cause of Repa
amount of Da
besides being
dates and ini
damage cas
Offered his
as a damage
d the Surveyor
"
this was not
d what parts
to what specia
Surveyor to a
te latest date
the Surveyor
the Surveyor
the Surveyor
the Surveyor
the Surveyor
screw shaft
s shaft now
s the shaft
te date of ex
Engine p
the Survey i
Yow
about
neral
(State clear
any
ELM
O
ew,
as c
y Fee (per
pecial Damage