

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

No. 1 SURVEY PARTLY HELD.

VESSEL'S NAME Sik. S.S. MUDDEA Rpt. Bry. No. 18863

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Subject — A bower anchor ~~to be~~ supplied + a broken length of cable disconnected

The S.S. No. 1 due 6.23 has now been partly held as

follows:-

A bower anchor + 7 1/2 fms of chain cable of proper size, weights + test supplied.

RETAIN

and the following repairs done (due to wear + tear) :-

Minor repairs effected.

It is proposed to complete the survey not staked

It is submitted ~~this proposal might be approved,~~ and the vessel be allowed to remain as classed, record of Survey and notation of S.S. No. 1 being deferred until completion of same.

Without conditions re anchor or cable

T.P.  
30.7.23

The following remains to be done to complete the S.S. No. 1

viz:- See Report.

[Signature]



© 2020

Lloyd's Register Foundation

W525-0163